

**Installation photos record**

Project: ASML Hong Kong Office

Date: 21 July 2018

Ventilation Opening before treatment



Seal up a part of opening by steel plate



Completed installation conditions



